



Release Notes for WaveSurfer 3000 Firmware Version 7.5.1.3

Summary of Changes:

- Fixed an issue where active probes were not always detected properly
- Fixed an issue where saving and recalling waveforms from a sequence mode acquisition didn't work correctly
- Fixed an issue where the zoom trace in WaveScan didn't work correctly when the source was a digital channel or group
- Fixed an issue where Decode2 didn't properly decode waveforms